

ship June 10

Work Order ID 147043

Monday, May 30, 2016 8:53:49 AM

147043

Page 1

Item ID: D412-711-021 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Vertical Reference Door Modification LH
 Start Date: 5/31/2016 Start Qty: 1.00 ***1*** Cust Item ID:
 Required Date: 6/10/2016 Req'd Qty: 1.00 ***1*** Customer:
 Reference:

Approvals: Process Plan: dm Date: 16/05/30 Tooling: _____ Date: _____
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____
 Run Start ***NR1***
 Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D412-711	K								
100	Document Control	0.00							
100	DOCUMENT CONTROL								
DC	Memo	0.00							
Doc.Control -USB or Paperwork	Photocopy bluefiles and create labels per PPP D412-711-021 CHG002								
120	Pick Kit	0.00							
120	Purchasing								
Packaging	Memo	0.00							
Packaging									
130	QC4- 100% Inspect kits for completeness	0.00							
130									
QC	Memo	0.01							
Quality Control									

MAY 31 2016

DAS
6
9-89

DAS
27
9-89

MLS 1606-01

DAS
6
9-89

DAS
28
9-89

JUN 01 2016

DAS
27
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS					
Part No. _____		Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐		
NCR No. _____		Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐		
		Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐		
		Large Fab ☐	Composite ☐	Supplier ☐			

Date : _____	Step #: _____	QTY Effective : _____	MRB (QSI042) Approval
Description Work Order Deviation		Disposition	Completed By
			Lead hand / Supervisor Approval Verification
			QC / QA Coordinator Approval

Root Cause			FAULT CATEGORY			
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	
Past Expiry Date ☐	Manufacturing Process ☐					
Misidentified ☐	Past Due ☐	OTHER : _____				

Work Order ID 147043***147043***

Page 2

Monday, May 30, 2016 8:53:49 AM

Item ID: D412-711-021

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Vertical Reference Door Modification LH

Start Date: 5/31/2016 Start Qty: 1.00 ***1***

Cust Item ID:

Required Date: 6/10/2016 Req'd Qty: 1.00 ***1***

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

150

0.00

150

Packaging

Memo

0.00

Identify and pack for shipping as per PPP D412-711-021

Location: _____

PPP rev: _____

b 105

DAS

27

9-89

DAS
28
9-89

160

QC21- Final Inspection - Work Order Release

0.00

160

QC

Memo

0.02

Quality Control

JUN 09 2016

MLJ JUN 10 2016

MLJ JUN 10 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Monday, May 30, 2016 8:54:04 AM

147043

D412-711-021

Required Date: 6/10/2016

Required Qty: 1.00

IPP Rev:B

[illegible]

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : ☐					

Picklist Print

Page 2

Monday, May 30, 2016 8:54:04 AM

Work Order ID: 147043

147043

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 5/31/2016

Required Date: 6/10/2016

Start Qty: 1.00

Required Qty: 1.00

D4165-5 Manufactured No 120 Each 5.0000 1 1

D4165-5

Aft Rib

DAS
27
9-89

Location

Loc Qty

Loc Code

ST236

5

143362

5

D4165-7 Manufactured No 120 Each 9.0000 1 1

D4165-7

Fwd Rib

DAS
27
9-89

Location

Loc Qty

Loc Code

ST236

9

116604

9

D4165-9 Manufactured No 120 Each 1.0000 1 1

D4165-9

Angle

DAS
27
9-89

Location

Loc Qty

Loc Code

ST237

1

119607

1

D4165-11 Manufactured No 120 Each 6.0000 1 1

D4165-11

Door Cover Panel

DAS
27
9-89

Location

Loc Qty

Loc Code

st238

6

141938

6

D4207-1 Manufactured No 120 Each 6.0000 1 1

D4207-1

Window Retainer

DAS
27
9-89

Location

Loc Qty

Loc Code

ST237

6

141942

6

Monday, May 30, 2016 8:54:05 AM

Shop Packet Print

Page 2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		

Root Cause				FAULT CATEGORY			
Environment ☐	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐
Design ☐	☐	Operator	☐	Bending	☐	Set-up	☐
Doc/Data ☐	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐
Equip/Tooling ☐	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐
Handling/Pre ☐	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐
Material ☐	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐
Internal Transport ☐	☐	Poor Information	☐	Crushing	☐	Countersink	☐
Tribal Knowledge ☐	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐
LOA ☐	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐
Substation ☐	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐
Past Expiry Date ☐	☐	Manufacturing Process	☐	OTHER : ☐			
Misidentified ☐	☐	Past Due	☐				

Picklist Print

Page 3

Monday, May 30, 2016 8:54:05 AM

Work Order ID: 147043

147043

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 5/31/2016

Required Date: 6/10/2016

Start Qty: 1.00

Required Qty: 1.00

D4207-3 Manufactured No

120 Each 2.0000 1 1

D4207-3

Instrument Window

**

DAS
6 28
9-89 9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

ST237

2

142232

2

D4269-1 Manufactured No

120 Each 1.0000 1 1

D4269-1

Angle

**

143364

DAS
6 28
9-89 9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

ST089

1

144018

1

D4269-3 Manufactured No

120 Each 6.0000 1 1

D4269-3

Angle

**

DAS
6 28
9-89 9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

ST089

6

141939

6

D4269-5 Manufactured No

120 Each 1.0000 1 1

D4269-5

Angle

**

143365

DAS
6 28
9-89 9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

ST237

1

144019

1

D4269-7 Manufactured No

120 Each 0.0000 1 1

D4269-7

Angle

**

145763

DAS
6 28
9-89 9-89

DAS
27
9-89

Monday, May 30, 2016 8:54:05 AM

Shop Packet Print

Page 3

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐							
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval				
Description Work Order Deviation				Disposition				Completed By			
Root Cause				FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐		No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐		Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐		Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐		Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐	
OTHER : ☐											

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

Monday, May 30, 2016 8:54:05 AM

Required Qty: 1.00

9-89

DAS
27
9-89

DAS
27
9-89

DAS
6
9-89

DAS
28
9-89

DAS
27
4-89

2000

DAS
27
9-80

DAS
DAS 28
6 9-89
9-89

JUN 01 2016
DAS 28
6 9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Picklist Print

Monday, May 30, 2016 8:54:05 AM

Work Order ID: 147043

147043

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 5/31/2016

Required Date: 6/10/2016

Start Qty: 1.00

Required Qty: 1.00

CR3242-4-2 Purchased No

120 Each 87.0000 34 34

CR3242-4-2

RIVET

DAS
27
9-89

Location

Loc Qty

Loc Code

ST318

87

m134500

87

34
135

DAS
28
9-89

MS20426AD3-3 Purchased No

120 Each 2,300.000 135

MS20426AD3-3

RIVET

DAS
27
9-89

Location

Loc Qty

Loc Code

GA

828

M131624

828

ST312

1472

M131624

1472

135

DAS
28
9-89

MS20426AD4-3 Purchased No

120 Each 1,851.000 140 140

MS20426AD4-3

Rivet

DAS
27
9-89

Location

Loc Qty

Loc Code

GA

1171

113064

171

m125807

1000

ST312

680

m125807

680

140

DAS
28
9-89

MS20470AD3-3 Purchased No

120 Each 6,297.000 25 25

MS20470AD3-3

RIVET, UNIVERSAL HEAD

DAS
27
9-89

Location

Loc Qty

Loc Code

GA

877

1065

877

ST310

5420

16941

5420

25

DAS
28
9-89
JUN 01 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : ☐					

Picklist Print

Page 7

Monday, May 30, 2016 8:54:05 AM

Work Order ID: 147043

147043

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 5/31/2016

Required Date: 6/10/2016

Start Qty: 1.00

Required Qty: 1.00

MS20470AD4-3

Purchased

No

120

Each

787.0000

90

90

DAS

6

9-89

DAS

28

9-89

MS20470AD4-3

Rivet - Universal Head

DAS
27
9-89

Location

Loc Qty

Loc Code

GA

760

2193

760

ST310

27

2193

27

MS21042L3

Purchased

No

120

Each

1,455.000

24

24

MS21042L3

Nut

DAS
27
9-89

Location

Loc Qty

Loc Code

FP001

82

m133790

82

GA

293

m133790

3

m134360

290

ST303

1080

m134039

12

m134634

468

m134754

600

DAS

6

9-89

DAS

28

9-89

JUN 01 2016

Monday, May 30, 2016 8:54:05 AM

Shop Packet Print

Page 7

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																													
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval																																																										
Description Work Order Deviation				Disposition				Completed By																																																									
								Lead hand / Supervisor Approval Verification																																																									
								QC / QA Coordinator Approval																																																									
Root Cause		FAULT CATEGORY																																																															
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____			
Misidentified ☐	Past Due ☐																																																																

Picklist Print

Page 8

Monday, May 30, 2016 8:54:05 AM

Work Order ID: 147043

147043

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 5/31/2016

Required Date: 6/10/2016

Start Qty: 1.00

Required Qty: 1.00

MS21059L3

Purchased

No

120

Each

195.0000

4

4

MS21059L3

Nut Plate

DAS
27
9-89

Location

Loc Qty

Loc Code

CA

8

M129682

8

GA

18

M133990

18

ST301

143

M134257

50

M134509

23

M134762

70

ST303

26

M133016

26

DAS
6
9-89
DAS
28
9-89

MS21069L3

Purchased

No

120

Each

79.0000

34

34

MS21069L3

ANCHOR NUT

DAS
27
9-89

Location

Loc Qty

Loc Code

ST299

79

m134676

79

DAS
6
9-89
DAS
28
9-89

MS21069L08 {

Purchased

No

120

Each

566.0000

8

8

MS21069L08

ANCHOR NUT

DAS
27
9-89

Location

Loc Qty

Loc Code

ST299

566

123522

566

DAS
6
9-89
DAS
28
9-89

JUN 01 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Picklist Print

Page 9

Monday, May 30, 2016 8:54:05 AM

Work Order ID: 147043

147043

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 5/31/2016

Required Date: 6/10/2016

Start Qty: 1.00

Required Qty: 1.00

MS21071L3

Purchased

No

120

Each

175.0000

3

3

MS21071L3

ANCHOR NUT

DAS
27
9-89

Location

Loc Qty

Loc Code

ST299

75

m129702

75

ST301

100

125654

100

**

DAS
28
9-89

DAS
28
9-89

3

MS21071L08

Purchased

No

120

Each

156.0000

1

1

MS21071L08

ANCHOR NUT

DAS
27
9-89

Location

Loc Qty

Loc Code

ST299

156

102587

56

103447

100

**

DAS
28
9-89

DAS
28
9-89

/

JUN 01 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

52.9 PARTS LIST

Qty -011	Qty -013	Qty -015	Qty -017	Qty -019	Qty -021	Qty -041	Qty -043	Part Number	Description
X								D412-711-011	VERTICAL REFERENCE DOOR INSTALLATION, 212/412
	X							D205-711-013	VERTICAL REFERENCE DOOR INSTALLATION, 205/210
		X						D204-711-015	VERTICAL REFERENCE DOOR INSTALLATION, 204
			X					D214-711-017	VERTICAL REFERENCE DOOR INSTALLATION, 214
				X				D212-711-019	VERTICAL REFERENCE DOOR EAGLE SINGLE
					X			D412-711-021	VERTICAL REFERENCE DOOR KIT
A ₁	A ₁	A ₁	A ₁	A ₁		X		D412-711-041	VERTICAL REFERENCE DOOR ASSEMBLY
							X	D412-711-043	SNAP VENT KIT
					1	1		D412-761-043	MODIFIED LATCH MECHANISM KIT, LH (REPLACES EA20469-23/-24/-25)
					1	1		D412-711-101	REPLACEMENT WINDOW (REPLACES EAGLE P/N EB212-100L / EA20469-3)
					1	1		D3802-1-120	RUBBER STRIP
							2	D3932-1	SNAP VENT
					1	1		D4165-1	DOUBLER
					1	1		D4165-3	DOOR INNER SKIN (REPLACES EA20469-18)
					1	1		*D4165-5	AFT RIB (REPLACES EA20469-34)
					1	1		**D4165-7	FWD RIB (REPLACES EA20469-31)
					1	1		D4165-9	ANGLE (REPLACES EA20469-17)
					1	1		D4165-11	DOOR COVER PANEL (REPLACES EA20469-21)
					1	1		D4207-1	WINDOW RETAINER (REPLACES EA20469-14)
					1	1		D4207-3	WINDOW (REPLACES EA20469-13)
					1	1		*D4269-1	ANGLE (REPLACES EA20469-33)
					1	1		**D4269-3	ANGLE (REPLACES EA20469-30)
					1	1		**D4269-5	ANGLE (REPLACES EA20469-29)
					1	1		*D4269-7	ANGLE (REPLACES EA20469-32)
					1	1		D4324-011	ARM REST ASSEMBLY (REPLACES EA20469-16)
					1	1		D4327-1	ANGLE (REPLACES EA20469-11)
					1	1		D4327-3	ANGLE (REPLACES EA20469-07)
					2	2		D4385-1	PLACARD

* PART OF EA20469-10 REAR RIB ASSEMBLY

** PART OF EA20469-12 FWD RIB ASSEMBLY

• COPYRIGHT © 2007 BY EAGLE COPTERS LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM EAGLE COPTERS LTD.

52-00-00

Revision: 2

Qty -011	Qty -013	Qty -015	Qty -017	Qty -019	Qty -021	Qty -041	Qty -043	Part Number	Description
					22	22		AN3-3A	BOLT
					20	20		AN3-4A	BOLT
					26	26		AN3-6A	BOLT
					1	1		AN3-12A	BOLT
					92	92		NAS1149F0332P	WASHER (OR AN960-10L)
					34	34		CR3242-4-2	RIVET
					135	135		MS20426AD3-3	RIVET
					140	140		MS20426AD4-3	RIVET
					25	25		MS20470AD3-3	RIVET
					90	90		MS20470AD4-3	RIVET
					24	24		MS21042L3	NUT
					4	4		MS21059L3	NUT PLATE
					34	34		MS21069L3	NUT PLATE
					8	8		MS21069L08	NUT PLATE
					3	3		MS21071L3	NUT PLATE
					1	1		MS21071L08	NUT PLATE
						1		204-030-853-125	LH COPILOT DOOR (204-030-853-137/-155)
1								D412-711-111	WIRING HARNESS, 212/412
^B 1								^B D4268-043	INSTRUMENT PANEL, 212/412 (REPLACES EA20469-15-412)
	1							D205-711-113	WIRING HARNESS, 205
	^B 1							^B D4268-041	INSTRUMENT PANEL, 205 (REPLACES EA20469-15-205)
		1						D204-711-115	WIRING HARNESS, 204
		^B 1						^B EA20469-15-204	INSTRUMENT PANEL, 204
			1					D214-711-117	WIRING HARNESS, 214
			^B 1					^B EA20469-15-214	INSTRUMENT PANEL, 214
					1			D212-711-119	WIRING HARNESS, EAGLE SINGLE
					^B 1			^B D4268-047	INSTRUMENT PANEL, EAGLE SINGLE

(A) IF CUSTOMER PREFERS TO SUPPLY AND MODIFY THEIR OWN DOOR, D412-711-021 SHOULD BE SUPPLIED IN LIEU OF D412-711-041.

(B) INSTRUMENT PANEL INCLUDED WITH HARNESS ABOVE.

• COPYRIGHT © 2007 BY EAGLE COPTERS LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM EAGLE COPTERS LTD.

52-00-00

Revision: 2

QTY -011	QTY -013	QTY -015	QTY -017	QTY -019	QTY -021	QTY -041	PART NUMBER	DESCRIPTION
					22	22	AN3-3A	BOLT
					20	20	AN3-4A	BOLT
					26	26	AN3-6A	BOLT
					1	1	AN3-12A	BOLT
					92	92	NAS1149F0332P	WASHER (OR AN960-10L)
					34	34	CR3242-4-2	RIVET
					135	135	MS20426AD3-3	RIVET
					140	140	MS20426AD4-3	RIVET
					25	25	MS20470AD3-3	RIVET
					90	90	MS20470AD4-3	RIVET
					24	24	MS21042L3	NUT
					4	4	MS21059L3	NUT PLATE
					34	34	MS21069L3	NUT PLATE
					8	8	MS21069L08	NUT PLATE
					3	3	MS21071L3	NUT PLATE
					1	1	MS21071L08	NUT PLATE
						1	204-030-853-125	LH COPILOT DOOR (204-030-853-137/-155)
1							D412-711-111	WIRING HARNESS, 212/412
^B 1							^B D4268-043	INSTRUMENT PANEL, 212/412 (REPLACES EA20469-15-412)
	1						D205-711-113	WIRING HARNESS, 205
	^B 1						^B D4268-041	INSTRUMENT PANEL, 205 (REPLACES EA20469-15-205)
		1					D204-711-115	WIRING HARNESS, 204
		^B 1					^B EA20469-15-204	INSTRUMENT PANEL, 204
			1				D214-711-117	WIRING HARNESS, 214
			^B 1				^B EA20469-15-214	INSTRUMENT PANEL, 214
				1			D212-711-119	WIRING HARNESS, EAGLE SINGLE
				^B 1			^B D4268-047	INSTRUMENT PANEL, EAGLE SINGLE

(A) IF CUSTOMER PREFERS TO SUPPLY AND MODIFY THEIR OWN DOOR, D412-711-021 SHOULD BE SUPPLIED IN LIEU OF D412-711-041
(B) INSTRUMENT PANEL INCLUDED WITH HARNESS ABOVE

NOTES

1) WIRING HARNESSES:

For Bell 204/205/210/214 Wiring Harnesses, use drawing D2046904.

For Bell 212 Wiring Harnesses, use drawing D2046903*.

For Bell 412 Wiring Harnesses, use drawing D412-711-901.

For Bell 212 modified per SH07-28/SR02831NY use D212-761-224 or D212-761-225 depending on aircraft s/n.

* Despite the note on the drawing, D2046903 is applicable to all 212 aircraft serial numbers

Wiring Harnesses will vary depending on aircraft s/n.

2) D412-711-101 REPLACEMENT WINDOW:

To increase downward viewing clarity, it is acceptable to cut a small section from the replacement window on its downward side per Figure 1 of this document. The cutout can be a maximum of 9.00" wide x 17.00" long (229mm x 432mm), measured along the profile of the replacement window. The corners of the cutout must have a minimum radius of 2" (50mm). The cutout should be located at least 1.0" (25mm) from the flange. The actual shape of the cutout can vary as desired, as long as the overall dimensions are within the specified limits. See Figure 1 for reference.

3) D412-711-043 SNAP VENT KIT:

It is acceptable to install a total of up to 2X D3932-1 Snap Vents (available from Dart) onto the D412-711-101 Replacement Window to provide ventilation into the cabin. Refer to Figure 1 for acceptable locations and size of cutouts.

4) It is acceptable to use MS21042L3 nuts to install the window in lieu of anchor nuts shown on D2046901.

APPROVED

DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	RF		
CHECKED	DC	DRAWING NO.	REV. K
MFG. APPR.	JLM	D412-711	SHEET 3 OF 6
APPROVED	HS	TITLE	SCALE
DE APPR.	DS	VERTICAL REFERENCE DOOR	NTS
DATE	14.04.07	COPYRIGHT © 2004 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

QTY -011	QTY -013	QTY -015	QTY -017	QTY -019	QTY -021	QTY -041	QTY -043	PART NUMBER	DESCRIPTION
X								D412-711-011	VERTICAL REFERENCE DOOR INSTALLATION, 212/412
	X							D205-711-013	VERTICAL REFERENCE DOOR INSTALLATION, 205/210
		X						D204-711-015	VERTICAL REFERENCE DOOR INSTALLATION, 204
			X					D214-711-017	VERTICAL REFERENCE DOOR INSTALLATION, 214
				X				D212-711-019	VERTICAL REFERENCE DOOR EAGLE SINGLE
					X			D412-711-021	VERTICAL REFERENCE DOOR KIT
A1	A1	A1	A1	A1		X		D412-711-041	VERTICAL REFERENCE DOOR ASSEMBLY
							X	D412-711-043	SNAP VENT KIT
					1	1		D412-761-043	MODIFIED LATCH MECHANISM KIT, LH (REPLACES EA20469-23/-24/-25)
					1	1		D412-711-101	REPLACEMENT WINDOW (REPLACES EAGLE P/N EB212-100L / EA20469-3)
					1	1		D3802-1-120	RUBBER STRIP
							2	D3932-1	SNAP VENT
					1	1		D4165-1	DOUBLER
					1	1		D4165-3	DOOR INNER SKIN (REPLACES EA20469-18)
					1	1		* D4165-5	AFT RIB (REPLACES EA20469-34)
					1	1		** D4165-7	FWD RIB (REPLACES EA20469-31)
					1	1		D4165-9	ANGLE (REPLACES EA20469-17)
					1	1		D4165-11	DOOR COVER PANEL (REPLACES EA20469-21)
					1	1		D4207-1	WINDOW RETAINER (REPLACES EA20469 -14)
					1	1		D4207-3	WINDOW (REPLACES EA20469-13)
					1	1		* D4269-1	ANGLE (REPLACES EA20469-33)
					1	1		** D4269-3	ANGLE (REPLACES EA20469-30)
					1	1		** D4269-5	ANGLE (REPLACES EA20469-29)
					1	1		* D4269-7	ANGLE (REPLACES EA20469-32)
					1	1		D4324-011	ARM REST ASSEMBLY (REPLACES EA20469-16)
					1	1		D4327-1	ANGLE (REPLACES EA20469-11)
					1	1		D4327-3	ANGLE (REPLACES EA20469-07)
					2	2		D4385-1	PLACARD

* PART OF EA20469-10 REAR RIB ASSEMBLY
 ** PART OF EA20469-12 FWD RIB ASSEMBLY

APPROVED

DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	RF		
CHECKED	DC	DRAWING NO.	REV. K
MFG. APPR.	JLM	D412-711	SHEET 2 OF 6
APPROVED	HS	TITLE	SCALE
DE APPR.	DS	VERTICAL REFERENCE DOOR	NTS
DATE	14.04.07	COPYRIGHT © 2004 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	